

Allotments – Condition Survey of Structures Summary List – date 25.1.23

SITE	ISSUE	PROPOSAL	Estimated cost	2019-2020	2020-2021	2021-2022	2022-2023	2023-24
Lower Cornwallis	Central steps damaged	Reconstruction or repair	Funded from another budget	completed				
	Chestnut pale fence deteriorating	Replace or repair	£750- (brought forward from 2022-2023 charged to alternative budget, uprated spec. £1,895-)			Completed		
	Drainage tank cover damaged	Fence/secure location	£500				£500 review	Review/Revise estimate
Fernbank	Meter cover broken	Replace cover	No cost to HBC	Completed				
	Communal Shed gutter broken	Repair gutter and re-stain	£165		£397.64 completed			
Harley Shute								
Bembrook								
Pauls Field	Toilet out of commission	Remove shed and cap tap. Assess removal	Estimate costs					
	Concrete communal	Repaint door	£45		Completed £106.28			

	shed door rotten							
	Timber middle shed	Repairs and redecorate	£490		Completed £490-			
Choice	Rotten logs to DDA area	Remove and replace/make safe	£200		Completed £580			
	Benches and hand rail to DDA area in poor condition	Repaint/varnish	£150		Delay until 4/23		£150 (review)	Review/Revise estimate
	Compost toilet and ramp	Treat cladding and ramp	£560				£560 (review)	Review/Revise estimate
	Communal shed – asbestos roof damaged. Cracks to blockwork and overlapping asbestos panels. Ivy growing over	Repair flaking paint, treat and remove ivy	£280		Delay until 4/23, revise estimate		£280 (review)	Review/Revise estimate
Downs Road	Communal shed fascia – damaged	Cut back hedging to permit assessment of condition.	No cost to allot. Budget					
		Repair timber cladding and guttering	£200	Delay until 4/23			£200 (review)	Review/revise estimate
Lower Clive Vale	Railing fence – damaged	Repair	£200	Completed (actual cost £398)				

Tivoli	Main access gate – damaged	Repair	£1900				£1900 (review)	Review/revise estimate
	Concrete block store and asbestos roof	Repair cracking above door, install lintel, replace asbestos roof. (part funded from another budget) Door condition poor – door to be redecorated	£1850 £45	Completed (Actual cost £1850) Delay until 4/23 revise est.			£45.00 (review)	Review/revise estimate
Collier Road	Main entrance gate – severely corroded frame	Replace onto existing posts	£1500			Delay until 4/23 and review	£1500 (review)	Review/revise estimate
	Fence posts leaning – West Hill boundary	Put vertical	£500				£500 (review)	Review/revise estimate
	Fence to 15 Collier Road - damaged	Replace	£500				£500 (review)	Review/revise estimate
	Communal shed – structural cracks	Monitor Fit tell tales.	£53.50		£179.50 completed			
BOS Field	Plastic tank – broken	Replace	£200		Delay until 4/21	completed		
	Communal shed – roof damage	Replace roof panel, cut back overgrown vegetation to assess condition,	£300 £53.50		Delay until 4/23		£300 (review)	Review/revise estimate

		Monitor cracking. Fit tell tales.				£53.50 completed		
Apps Field	Door – Poor quality	Redecorate	£45			£79.36 completed		
	Galvanised tanks causing obstruction, containing debris and rubbish	Empty and return to use	£300		Delay until 4/23		£300 (review)	Review/revise estimate
Total			£11,932.00	£2248.00	£1753.42	£692.86	£6735.00	Re-evaluate project costs and against current priorities